CORNER RESTORATION



SW Cor.
CORNER Sec. 3 **TWP** 13 S. **RANGE** 33 E.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869

ORIGINAL DESCRIPTION:

Set Stone 16x10x5 for Corner to Sections 3, 4, 9 & 10.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
J. L. Watson
K. J. Workman

December 7, 1988

RECEIVED AND FILED
JAN 3 1989
OFFICE OF COUNTY SURVEYOR
Attest: Robert D Bagett John L Watson

REGISTERED PROFESSIONAL LAND SURVEYOR
Robert D Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598
Grant County Surveyor

EVIDENCE FOUND:

I found the original basalt corner stone, 18x9x6 inches marked with 3 grooves on East face and 5 grooves on South face. I accept the position of this stone for the section corner.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

At the Corner Point: Set a 1½"x30" galv. iron pipe 28 inches in the ground with attached brass cap marked as shown; From which I set NEW REFERENCE POINTS:

A 5/8"x30" iron pin with attached 1½" Aluminum Cap bears N. 45° E. 30.00 ft., marked Grant County Surveyor RPI 1988.

A 5/8"x30" iron pin with attached 1½" Aluminum Cap bears S. 45° E., 30.00 ft., marked Grant County Surveyor RP2 1988.

A 5/8"x30" iron pin with attached 1½" Aluminum Cap bears S. 45° W., 30.00 ft., marked Grant County Surveyor RP3 1988.

A 5/8"x30" iron pin, with attached 1½" Aluminum Cap bears N. 45° W., 30.00 ft., marked Grant County Surveyor RP4 1988, set in a East-West fence line.

MONUMENT MARKED

GRANT COUNTY SURVEYOR
T13S R33E
S4 | S3
S9 | S10
1988
OPLS598

Buried marked stone, South, and alongside the iron pipe. This corner falls in a North-South fence line, 20 feet South of a fence corner - fences running North-South and West.

Used magnetic compass with 20° E., variation and steel tape for measurements to reference points.

No bearing trees or bearing objects available.

E-13