

Parties notified were W J Galbraith, Mrs Muldrick, Wm Hall Jr, T M Ficks, Harry Smith Bros

Met at Smith Bros Ranch Nov 11 1909 and proceeded to S 1/4 corner Sec 14 T13R32E  
When Frank Howell, & John E Street and Wm Hall Jr were sworn in Flaman & Chairman

|     |     |                                                   |
|-----|-----|---------------------------------------------------|
| Ch  | Sta | East from S 1/4 Cor Sec 14 T13R32E                |
| 40  | 00  | SE Cor Sec 14 missing                             |
| 60  | 00  | set Temp 1/4                                      |
| 80  | 00  | N 1/4 Cor Sec 24 missing                          |
| 100 | 00  | set Temp 1/4                                      |
| 120 | 55  | The SE Cor Sec 13 Hall North 67                   |
|     |     | North from SE Cor Sec 13                          |
| 20  | 00  | set Temp                                          |
| 40  | 00  | E 1/4 Cor Sec 13 missing                          |
| 60  |     | set Temp 1/4                                      |
| 80  | 50  | The NE Cor Sec 13 facing W 48                     |
|     |     | West from NE Cor Sec 13                           |
| 20  | 00  | set Temp 1/4                                      |
| 40  | 86  | The N 1/2 Cor Sec 13 fall S 60                    |
|     |     | West from 1/4 cor                                 |
| 20  |     | set Temp                                          |
| 40  | 49  | The NW Cor Sec 13 fall south 50                   |
|     |     | South from NW Cor Sec 13                          |
| 20  | 00  | set Temp 1/4                                      |
| 40  | 40  | The W 1/4 Cor Sec 13                              |
| 60  |     | South from W 1/4 Cor Sec 13                       |
| 20  |     | set Temp 1/4                                      |
| 40  |     | Sec Cor Miss set above                            |
| 80  |     | 1/4 Cor missing                                   |
| 120 |     | The Sec Cor miss (Sec 24 SW corner)               |
| 140 |     | The E 1/4 Cor Sec 26 <sup>T13R32E</sup> fall W 50 |

Now established the S 1/4 Cor Sec 13 at its proper proportion distance according to our  
measurements & the Gov Field Notes

Corrected all the temporary Corners to their proper proportional distances and positions  
And then ran straight lines across the Section from opposite 1/4 corners  
and at their intersection set the center of Sec 13 & then crossed the lines from opposite 1/4 corners  
of the quarters and at their intersection set Center of the quarters  
I plainly Chiseled the marks on the Corners set them well with mound of Rich

For Cuts see next leaf over.