

chains links

After duly qualifying on oath L R Boyad and Henry Huppert as chainbearers and S B Parrish as flagman and marker. I proceeded to make the following survey.

Commencing at corner to sections 1 and 2 on both boundary of Township 14 South Range 31 East which is a stone 18 x 12 x 5 inches in a mound of stone in good condition and running west on special standard line between Townships 13 and 14 South

20

set temporary 1/4 section corner

36

52

find section corner to sections 34 and 35 T13 S. R 31 E in bad condition. restored corner by placing granite boulder stone 6 x 7 x 18 inches marked with six notches and $\frac{13}{31}$ on north face and raised stone mound around corner

40

00

placed temporary 1/4 section corner

I then commenced at sec cor to sections 2 and 3 which is a stone 24 x 22 x 14 ins in mound of stone and marked thus $\frac{22}{24}$ and run East on true line bearing $20^{\circ}30' E$,

40

22

to temp 1/4 section corner and established permanent 1/4 sec corner which is a stone 6 x 8 x 15 inches marked thus $\frac{14}{24}$ on south face and raised stone mound around corner.

Thence South bearing $20^{\circ}10' E$ on line perpendicular to Township line

16

66

which by computation of field notes of East and west boundaries of section I find to be the distance between lots 2 and 3 and placed temp cor

36

66

place temp cor for legal centre of section

56

66

find no 1/4 sec cor as indicated in field notes of United States Survey. believing 1/4 cor to be destroyed. I then established at 36.66 a centre monument which is a stone 8 x 12 x 14 ins in mound of stone and marked to

State of Oregon }
County of Grant } ss.

I hereby certify that I made the foregoing survey and established the corners as described.

Dated this 18th day of September 1897

A F White

County Surveyor