

Commence at the S.E. corner of section 5, T.13, S.R.33 E.W.1.

which is a stone well marked and set. Thence

North

80.50 To point for N.E. corner of section 5, T.13 S.R.33 E.W.1. which being obliterated I reestablish, with stone 16"x5"x4" set in round of stone sbiseled 4 notches east and 2 notches west.

Return to the S.E. corner of sec 5-13-33 thence west on random line

80.6 To S.W. corner of sec. 5-13-33 which is a large rock well marked. If line falls one chain north of corner therefore run thence

N. 89 17' E. on true line

40.3 Establish 1/4 corner, Rock 14"x 6"x 5" set in round of stone chiseled 1/4 C.S.

Return to S.W. corner of section 5-13-33 thence.

North on true line.

80.5 Establish N.W. corner of section 5-13-33 rock 18"x 6"x 4" chiseled 5 notches east and 1 notch west C.S. thence north on random line.

70.00 Bear Creek 8 links wide flows S.W.

80.0 pt for cor.

Return to N.E. corner of section 5-13-33. thence,

North on true line

43.0 gulch bears N. 30 W.

75.0 gulch bears north and south.

80.71 Old corner secs 32-33-29-28-T.12 S.R.33 E.W.1. stone well marked and set. thence

North.

40.0 Establish corner 1/4 corner of sections 28-29-12-33 thence

80.0 Establish corner of secs 20-21-28-29-12-33 rock 18"x 8"x 6" set in a round of stone chiseled 2 notches south and 4 notches east. thence,

40.0 North

40.0 Establish corner 1/4 corner of sections 20-21-12-33 stone 16"x 8"x 6" in round of stone whence yellow pine 30" in diameter bears N. 55 48' W- 24.5 feet. blazed and scribed 1/4 C.S. Rock chiseled 1/4 C.S. thence,

East

80.5 to fence bearing north and south.

Return to cor. 20-21-28-29 thence.

West.

40.3 Establish corner 1/4 corner of secs. 20-21 rock 12"x10"x4" set in round of stone sbiseled 1/4 C.S.