

Application Survey FR 5 ch
A B L Smith

Traverse E 1/2 S W 1/4 S 1/2 S E 1/4 Sec 28
T 12 S R 32 E W W

Survey # 8

A L Gurnsey T 16 S R 31 E W W

Com at S W cor Sec 26. Then on
random line East

80 chs Sec line to 25-26-35-36
Then East

20 chs to S W cor A Gurnsey HW
East

60 " N W cor Sec 36 a post badly decayed and
East

20 chs to SW cor A G. homestead
SE 1/4 S W 1/4 S 1/2 S E 1/4 Sec 25 T 16 S R 31 E
and S W 1/4 S W 1/4 Sec 3 T 16 S R 32 E W W
Then East

20 chs to S W cor A L Gurnsey Desert
East

20 Sec line bet 30-31-29+32
East

20 chs S E cor A G Desert
S 1/2 S E 1/4 Sec 30 S 1/2 S W 1/4 Sec 29 T 16 S
R 32 E W W

C Southworth by A B Gurnsey
acting sham

22-32

16-31