

We find that the found junior Gradon corners fall between 1.2 feet and 10.9 feet from the senior McCornack Survey line, based on the corners found during our survey. The pipe set by Mr. McKinney is located 24+ feet West of the senior survey line. If we had been able to locate acceptable original evidence of the original corner monument at the location of Mr. McKinney's pipe, then we could have accepted the pipe as the perpetuation of the original corner monument. Due to the absence of original corner evidence and considering conversations with landowners, our survey data and correspondence with the Bureau of Land Management, I conclude that the original corner location is lost and re-establish the position as recommended by the Bureau of Land Management.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106