township corner using the record distances returned by Mr. Lackland's retracement.

I set the SW corner of Section 32, T12S, R31E at single proportion between the township corner and the SE corner of Section 32 and on the latitudinal curve. The NE and SE corners of the W1/2W1/2 of Section 32 were established in the usual manner as prescribed in the 1973 BLM Manual of Surveying Instructions. The north, south and east lines of Mr. Ferrioli's property were staked for fencing.

Cornerstone Surveying, Inc. 233 S. Canyon Blvd. John Day, Oregon 97845

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON SEPTEMBER 19, 1995

JACK L. WATSON 2734

RENEWAL DATE: 6/30/2002

RECEIVED AND

July 18,200/

Attest: We Manager