



Scale 1"=20'

BASIS OF BEARINGS

Survey No. 1668

LEGEND

- Found 5/8" iron pin with attached red plastic cap, see Survey No. 1668 unless otherwise shown.
- Set 5/8"x30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.
- x—x Fence Line
- () Record bearing and distance.
- Found monument, see record map of survey number shown in box.

NARRATIVE

This survey was performed at the request of Roger Lang. The purpose of this survey was to survey and monument a proposed boundary line adjustment.

A search was made of the available records pertaining to this survey. Field measurements were made to locate the existing monuments and to establish the new monuments for the proposed boundary adjustment.

I found and accepted the monuments shown hereon and established the new monuments in accordance with the evidence found.

RECEIVED AND
FILED

July 26, 2007
OFFICE OF COUNTY SURVEYOR
Attest: *[Signature]*

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
SEPT. 19, 1995
JACK L. WATSON
2734

Renewal Date 6/30/2008



CORNERSTONE SURVEYING, Inc.
 233 S. Canyon Blvd., John Day, Oregon 97845
 (541) 575-1813

MAP OF SURVEY
 PROPOSED BOUNDARY LINE ADJUSTMENT
 IN LOTS 3, 4, 9 AND 10 OF BLOCK C, TOWNSITE OF DAYVILLE
 SITUATED IN THE SE1/4 OF SECTION 1, T13S, R26E, W.M.
 CITY OF DAYVILLE
 GRANT COUNTY, OREGON

SURVEYED FOR: **Roger Lang**

SURVEYED BY : Jack Watson Date: 7/9/2007

DRAWN BY : Jack Watson

MAP OF SURVEY NO. ~~1668~~
1613