
Vicinity Map



SHEET INDEX

Sheet 1 . . . Vicinity Map and Narrative

Sheet 2 . . . Northeast portion of property boundary Sheet 3 . . . Northwest portion of property boundary Sheet 4 . . . Southwest portion of property boundary Sheet 5 . . . Southeast portion of property boundary

Sheet 7 . . . Surveyor's Certificate, Declaration, Approvals

I do hereby certify that this is a true and exact copy of original Land Partition plat.

Jack Watson, PLS

Bank of Eastern Oregon has consented to this re-plat partition and declaration by an Affidavit of Consent recorded in Instrument No. 2022 0977 in the office of the Grant County

REFERENCES

Grant County Deed Records Book 49 Page 281 Book 80 Page 118

Book 92 Page 450

Inst. No. 931271 Inst. No. 931327

Inst. No. 950935 Inst. No. 993088 Inst. No. 20201551

Inst. No. 20082784 Inst. No. 20082785

Inst. No. 20091741 Inst. No. 20211072 Inst. No. 20211073

Survey No. 1079 Survey No. 1825 Survey No. 1849 Survey No. 1858

Partition No. 98–06 Partition No. 98–24 Partition No. 2000-16 Partition No. 2021-08

Plat of Old Town of Monument Highway Drawing No. 6B-20-5

LAND PARTITION PLAT NO. 2022 - 06

A RE-PLAT OF PARCEL 1 AND PARCEL 2 OF LAND PARTITION NO. 2021-08 SITUATED IN THE SW1/4 AND THE NW1/4 SECTION 1

T9S, R27E, W.M. TOWN OF MONUMENT GRANT COUNTY, OREGON

May 4, 2022

Sheet 1 of 7



Scale 1"=400'

BASIS OF BEARINGS

Survey No. 2055

Between found ODOT pin near Initial Point and the East corner of Parcel 3, LP 98-24

REGISTERED

PROFESSIONAL

LAND SURVEYOR

OREGON

SEPT 19, 1995 JACK L. WATSON

2734

Renewal Date 6/30/2022

This survey was performed at the request of Josh Hamilton. The purpose of this survey was to re-plat Land Partition No. 2021-08, which is recorded in the office of the Grant County Clerk. Mr. Hamilton's property is described in Instrument No.'s 20201551 and 20211073 deeds of grant

A search was made of the available records pertaining to this survey. Field measurements were made to locate the existing monuments and the new corner position. The boundaries of Parcel 2 were adjusted at the direction of Mr. Hamilton.

I accept the found monuments as shown.

- Found 2½" Grant County Surveyor brass
- Found 5/8" iron pin with attached red plastic cap, unless otherwise shown.
- Found 5/8" iron pin with attached 2" alum.
- Set 5/8" X 30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.
 - Found monument, see record map of survey number shown in box.
- GLO record bearing and distance.
- Survey No. 669 record bearing and distance.
- Survey No. 1079 record bearing and distance.
-) Survey No. 1849 record bearing and distance.
- Survey No. 1858 record bearing and distance. Survey No. 2055 record bearing and distance.
- Survey No. 2154 record bearing and distance.
- Survey No. 2159 record bearing and distance. Partition No. 96-02 record bearing and distance.
- Partition No. 98-06 record bearing and distance.
- Partition No. 98-24 record bearing and distance. Partition No. 2000-16 record bearing and distance.
- Partition No. 2009-11 record bearing and distance.
- Deed Bk 92, Pg 448 record bearing and distance.
- Deed Bk 49, Pg 191 record bearing and distance.
- Inst. No. 931271 record bearing and distance.
- Inst. No. 20211073 record bearing and distance.
- Inst. No. 20082785 record bearing and distance.
- Highway Drawing No. 6B-20-5
- Partition No. 2021-08 record bearing and distance for Parcel 2.

NOTE: The dimensions shown for Parcel 1 are identical with the record dimensions shown on Land Partition No. 2021-08.