

SITUATED IN THE SE1/4 OF SEC. 27 AND IN THE NE1/4 OF SEC. 34
AND IN THE NE1/4 AND NW1/4 OF SEC. 35, T12S, R26E, W.M.
GRANT COUNTY, OREGON

[illegible]

SURVEY NO. 1443 AS SHOWN

- Found 2½" aluminum pipe with attached 2½" aluminum cap see Survey No. 1443.
- Found 1½" iron pipe with attached 2½" brass cap, see Survey No. 7G.
- Found 3" iron pipe with attached 3" BLM brass cap, see Survey No. 130.
- Found 5/8" iron pin with attached yellow plastic cap marked "PLS 848", (unrecorded).
- Set 5/8"x30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.
- ◎ Set 5/8"x30" iron pin with attached 2" alum. cap see corner restoration records for details.

X——X Fence Line

() Record bearing and distance.

NOTES:
1) The high water line and the 100 year flood hazard along the John Day River has not been determined.
2) The area for this partition is taken from the Grant County Assessor's records, and may vary when the lines of parcel 1 are determined by survey.

OREGON
SEPT 19, 1995
JACK L. WATSON
2734