

50079

Book "1" Page 157

Sept 6, 1963
 305 N. W. 5th. Ave.
 John Day, Oregon

Mr. Harold Patterson, County Surveyor
 Grant County Court House
 Canyon City, Oregon

Dear Mr. Patterson,

I have completed a re-survey of the Section Line common to Sections 8 and 17, T14S, R33E. Following is data pertinent to this survey:

Section Corner common to 7, 8, 17, and 18. T14S, R33E

Original mound of rock was in place.

Two bearing trees were found for this corner.

A Pine 28" diam. (stump) bears N 82° E 26 lks. distant.

A Mahogany 10" diam., bears S 68° W 19 lks. distant.

(Original notes called for one bearing tree a Pine 30" diam. bearing N 30° E 25 lks. distant.)

I set a 2" x 24" iron pipe with brass cap in original mound of rock. Cap was marked as follows:

7	8
18	17

T14S, R33E

From this Corner I ran east to the Section Corner common to Sections 8, 19, 16, and 17 T14S, R33E.

Original Corner rock in mound of rock was found.

Two bearing trees were found for this corner.

A Pine 30" diam. (snag) bears S 59° W 44 lks. distant.

A Pine 16" diam. (snag) bears S 64° E 1:00 Ch. distant.

(Original notes called for one bearing tree A Pine 30" diam. bearing S 50° E 50 lks. distant.)

Scribing on Bearing Trees was correct as to their respective locations.

My measured distance between the two above mentioned corners was 81.43 Chains.

At a point on line and mid-way between the two said corners, I established the One-Quarter Corner common to sections 8 and 17, T14S, R33E.

A 2" x 24" iron pipe was set in the ground with brass cap scribed as follows:

8
7

$\frac{1}{4}$ Cor., T14S, R33E