No.

History of original corner establishment:

local resident contacted.

Original corner set in 1874 by G. L. O. by private contractor. Field notes call for an ummarked rock 10 x 8 x 8. No accessories noted. No other ties in any direction except the adjacent section corners. No knowledge of this corner could be obtained from any

Description of corner evidence found:

None found. Corner re-established at mid point between adjacent

Monument consists of a  $2\frac{1}{2}$  inch brass disk welded to the top of a 2 inch galvanized iron pipe, approximately 30 inches in length, buried approxim 20 inches in the ground with a mound of rock set around the base. Flat piece of steel is welded to the base of the monument.

Disk is stamped with Metal dies as follows:

From which:
A 10" W.F. bears N 740 W
A 11" W.F. bears S 820 30' E 36.5 links 41 links

buried approximately s 4

State of ..... ...... , I hereby certify that the within instrument was filed in this office for record on the ...... day of ...... ....., 19......, at....... o'clock .....m., (signed) (COUNTY OFFICIAL) (DEPUTY)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(Reference FSH 5681.65)

Section 4

S 4 N. W. W. 11" w.F.

signature Workello G. Fallyno Dated at Burns, Orego Registration No. Title Land Surveyor

Page 161

...Burns, Oregon.

On this 16they of Ovember ....., 1964 State of .... Oregon. County of Harney before me, a notary public in and for said state, personally appeared

original location of this corner

Description of monument and accessories I established to perpetuate the

#53864

to me to be the person whose name is who acknowledged to me that he exesubscribed to the within instrument and Barcellus A. Palmer, known

Residing of Barney County, Ore. NOTARY PUBLIC)

1800

27. 15.05

Form R6-5680-182