

April 1st at 1^{pm} We met at SW Cor Sec 4, Twp 11 S R 30 E. There was present
E W Mulligan, Martin Dunlap, Phillip Adkins, M W Adkins, R. A. Adkins
All Land Owners in Sec 4 and adjoining Section. All mutually agreed to P. A. Adkins & J. E. Adkins
acting as Chainmen. P. A. Adkins & J. E. Adkins were sworn as chainmen

Beginning at SW Cor Sec 4 which is in good condition N 1° 33' W.

20

set Temp 1/4 Cor

40

1/4 Corner missing set Temp

79

29

NW Cor Sec 4 Missing " " or rather misplaced lying loose on top of ground

Thence East (True Mer)

40

The E 1/4 Cor Sec 33 T 10 S R 30 E Missing set Temp

80

22

" SE Cor Sec 33 fall S 4 links

Back and correct ^{Sec 33 T 10 S R 30} 1/4 Cor and also NW Cor Sec 4 T 11 R 30. Marked the Rocks set at these Corners properly

Proceeded to ^{Temp} W 1/4 Cor Sec 4 and corrected 11 links E. Set Rock 10x14x16. Marked 1/4 CS. Corner which (see blks)

From W 1/4 Cor Sec 4 R 87° 59' E (to match the 2 chs difference of E & W lines as given in Field Notes)

20

Set Temp 1/4

40

" " Centre

60

" " 1/4

80

88

The E 1/4 Cor Sec 4 falling 194 lbs North. I therefore conclude that the difference in lines as given field notes must
be erroneous. However we found the 1/4 corner plainly marked. And the Witness Trees down and
fast fading away the Witness Mark on one Tree was plainly to be seen. the other partly burned
also the Corner was not in right position & planted it where it belonged according to the Old
Witness Trees & Blazed Trees more as follows. A Pine 14' Dia S 0° 40' E 304 lbs. A Pine 16' Dia
306 lbs S 22° 15' W

Now begin at East 1/4 Cor Sec 4 T 11 R 30. Run Due South True mer

20

set Temp 1/4 cor

40

18

The SE Cor Sec 4 fall 9 lbs West. This Corner was missing. Mr Henry Behme an Old
Man and Land Owner Testified to the Original position. Witness M W Adkins J E Adkins
We set a Rock 8x10x10 in ground Marked one notch on North 5 notches on S & 3 notches on both E & West sides
Mr Henry Behme's Old Log Cabin (The NE corner) seen from this Rock S 70° W 55 lbs

Thence from The SE Corner Sec 4 T 11 R 30 South Due

20

set Temp 1/4 Corner

39

79

The 1/4 corner Witness trees down and decaying Blazed New One (is) Pine 36' (Shump's height) N 80° W 70 lbs

Proceeded to Temp 1/4 Cor ie (SE Cor & NE Cor Sec 4 T 11 R 30 and corrected and set at Marked a large Rock
(1/4 CS)

Proceeded to SE Cor Sec 4 ^{now} S 89° 35' W

20

set Temp 1/4 Cor

40

The 1/4 Corner in good condition fall S 17 lbs

Begin at S 1/4 Cor Sec 4 T 11 R 30 N 89° 35' W 205 lbs

20

set Temp 1/4 Corner

39

26

The Centre of Sec 4 Established by connecting the Temp Cor to proper position set Rock Marked 1/4 CS
fall W 16 lbs. set under old fence

Proceeded to Temp 1/4 cor on N line of SE 4 Sec 4 corrected set a Rock Marked 1/4 CS

40

Thence South to opposite 1/4

40

Thence from E 1/4 Cor of SE 4 Sec 4 West to opposite 1/4 cor at at this intersection set centre of SE 4 Sec 4
from which a Pine 12' Dia bears S 88° 25' W 42 lbs Marked BT
CS

See Plot for Corners Established

Witness Trees to W 1/4 Sec 4 T 11 R 30 A pine 8' Dia bears S 1° 05' W 255 lbs Marked BT CS

A pine 24' Dia bears S 70° 55' E 285 lbs Marked BT CS

Michael Spears County Surveyor