

Survey No 18

6hs

In T<sup>h</sup> 8 South Range 28 East & M

8-28

On application of H L Hines

After duly qualifying on oath I do Grubbe as Chamberlain and acting as Chamberlain and Marker myself.

I commenced at corner to sections 27, 28, 33 and 34 and run North bearing 22° 30' E on ~~intermediate course~~

40.00 find SW corner as indicated in field notes H L Survey

80.00 find section corner in good condition, which is a stone 8 x 15 x 17 ins in stone mound  
Juniper S 19° W 7 1/4 Sec BT 136 links dist

I then run south bearing 19° 50' E which I find by the back-sight to be the true line

40.00 established 1/4 sec cor (Book B Bearing Trees P 12)

60.00 established to the corner.

I then went to sec cor to secs 26, 27, 33 and 34 and run North bearing 24° 50' E on T C

40.25 find 1/4 sec cor in good condition

I then run back on same line South

20.12 placed stone 14 x 14 x 16 in stone mound for to cor marked CS. Thence W bearing 22° E

60.00 set to cor 8 x 10 x 14 ins in stone mound

from 1/4 sec cor on line bet-sec cor on line bet secs 26 and 27 and run East bearing 21° E

6.50 spring S of line 30 links dist

20.00 set stone 8 x 14 x 18 in stone mound for NE corner of N W 1/4 of S W 1/4 sec 26

I then run West bearing 21° E

60.00 placed stone 8 x 10 x 14 in stone mound marked to CS for NW Cor of N E 1/4 of S W 1/4 sec 27

Recorded Feb 26<sup>th</sup> February 2<sup>nd</sup> 1896

1896

W. White

County Surveyor