


## CORNER RESTORATION

CORNER W $\frac{1}{4}$  Sec. 26 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER: Unknown

CONTRACT DATE: 1873



**ORIGINAL DESCRIPTION:**

Set Basalt stone 12"x10"x6"

RESTORATION BY, STAMP AND DATE: June, 1970



*Handwritten signature of Duane I. Griffith*

JULY 10, 1964  
DUANE I. GRIFFITH  
644


**EVIDENCE FOUND:**

I do not identify the original stone.  
Fences running North, East, South and West.  
I accept these as being the best available evidence of the position of the original corner.

**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:**

Show how trees are scribed and basis of bearings, including compass var.

Set 1 $\frac{1}{2}$ "x30" iron post with Brass Cap Mkd.:  
Corner post to fences North & West bears N10°W, 7.6 ft. MONUMENT MARKED  
Corner post to fences South & East bears S18°E, 8.0 ft.  
No other accessories available. Grant County Surveyor



Complete and File with Office of the Grant Steel Tape & Compass  
County Surveyor, Grant County, Oregon, Var.=20° East  
Courthouse, Canyon City, Oregon 97820