


CORNER RESTORATION

CORNER NE TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Set stone 14"x 10"x 6"
 Fd. in retracement by Aaron York in 1880.

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:

NONE

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

Set 2 1/2" x 30" iron post with brass cap.

From which:

- A pine 9" diam. bears N58E; 47.5 ft.
 Mkd T11S R29E S30 BT
- A juniper 5" diam. bears S17E; 53.2 ft.
 Mkd T11S R29E S31 BT
- A pine 12" diam. bears S53W; 128.5 ft.
 Mkd T11S R28E S36 BT
- A pine 27" diam. bears N46 1/2 W; 90.0 ft.
 Mkd T11S R28E S25 BT

MONUMENT MARKED



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon, Steel tape & compass
 Courthouse, Canyon City, Oregon 97820 Var = 20° East