


CORNER RESTORATION

CORNER N $\frac{1}{4}$ TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Set stone 14"x 10"x 8"

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:

NONE

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2 $\frac{1}{2}$ "x 30" iron post with brass cap; set 12" below surface.

From which:

A pine 14" diam. bears N36W; 127.3 ft.
 Mkd T11S R29E $\frac{1}{4}$ S30 BT

A pine 26" diam. bears S63 $\frac{1}{2}$ W; 112.0 ft.
 Mkd T11S R29E $\frac{1}{4}$ S31 BT

A steel fence post bears S 89°12'05"W; 34.75 ft.
 A steel fence post bears N89°12'05"E; 34.75 ft.

MONUMENT MARKED

GRANT COUNTY SURVEYOR

T11S R29E
 S 30
 $\frac{1}{4}$
 S 31
 1969

LS 644

Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon, Steel tape & compass
 Courthouse, Canyon City, Oregon 97820 Var = 20° East