


## CORNER RESTORATION

CORNER NE TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



**ORIGINAL DESCRIPTION:**

Set stone 18" x 14" x 5"

**RESTORATION BY, STAMP AND DATE:**

**BAGETT & GRIFFITH SURVEYING**  
 170 S. DAYTON - PH. 575-1251  
 JOHN DAY, OREGON 97845

July 1969



**EVIDENCE FOUND:**

Fd. stone 18" x 14" x 5" broken into three pieces in a mound of stone, with a 2" + and one notch

**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:**

Show how trees are scribed and basis of bearings, including compass var.


Set 1 1/2" x 30" iron post with brass cap.

From which:

- A pine 34" diam. bears S63E; 153.3 ft.  
Mkd T11S R29E S32 BT
- A pine 32" diam. bears N63E; 96.0 ft.  
Mkd T11S R29E S29 BT
- A juniper 12" diam. bears N10W; 267.0 ft.  
Mkd T11S R29E S30 BT

**MONUMENT MARKED**

GRANT COUNTY SURVEYOR  
 T11S R29E



Complete and File with Office of the Grant  
 County Surveyor, Grant County, Oregon, Steel tape & compass  
 Courthouse, Canyon City, Oregon 97820 Var. = 20° East