


CORNER RESTORATION

CORNER N1/16 TWP 11S RANGE R29E

ORIGINAL SURVEY BY: Twp. sureved by William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Not set.

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
170 S. DAYTON - PH. 575-1251
JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2½" x 30" iron post with brass cap.


From which:

A tamarack 8" diam. bears S52E, 39.5 ft.
mkd N1/16 S32 BT

A tamarack 16" diam. bears S23W, 45.7 ft.
mkd N1/16 S32 BT

MONUMENT MARKED

GRANT COUNTY SURVEYOR



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon, Steel tape & compass
Courthouse, Canyon City, Oregon 97820 Var. = 20° East