


## CORNER RESTORATION

CORNER N1/16 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: Twp. surveyed by William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



**ORIGINAL DESCRIPTION:**

Not set

**RESTORATION BY, STAMP AND DATE:**

**BAGETT & GRIFFITH SURVEYING**  
 170 S. DAYTON - PH. 575-1251  
 JOHN DAY, OREGON 97845



July 1969

**EVIDENCE FOUND:**

None

**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:**

Show how trees are scribed and basis of bearings, including compass var.

Set 2½x30" iron post with brass cap.


From which:

A pine 8" diam., bears N37W, 27.2 ft.  
 Mkd. CN1/16 S32 BT.

A pine 16" diam., bears S75E, 10.2 ft.  
 Mkd. CN1/16 S32 BT.

**MONUMENT MARKED**

GRANT COUNTY SURVEYOR



Complete and File with Office of the Grant  
 County Surveyor, Grant County, Oregon, Steel Tape & Compass  
 Courthouse, Canyon City, Oregon 97820 Var = 20° East