


CORNER RESTORATION

CORNER W $\frac{1}{2}$ TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Set stone 12"x 10"x 8"

Fd. in retracement by Aaron York in 1880, who took bearing trees as follows;

A tamarack 24" diam. bears N40E; 12 lks.

A fir 20" diam. bears N10W; 10 lks.


RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845

July 1969



Duane I. Griffith



EVIDENCE FOUND:

Fd. stone and remains of two BTs.

A fir 20+" diam., dead and down, badly rotted showing signs of a blaze, bears N14W, 7 ft.

A dead tamarack 20 " diam., bears N75E, 10 ft. blaze, no scribes.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set iron post, 2 $\frac{1}{2}$ " x 30", with brass cap.

From which:

A pine 13" diam. bears S17E; 23.8 ft.

Mkd T11S R29E $\frac{1}{4}$ S31 BT

A fir 11" diam. bears S65W; 22.2 ft.

Mkd T11S R28E $\frac{1}{4}$ S36 BT

MONUMENT MARKED

GRANT COUNTY SURVEYOR

T11S

R28E | R29E

S 36 | S 31

1969
 LS 644

Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon, Steel tape & compass
 Courthouse, Canyon City, Oregon 97820 Var = 20° East