


CORNER RESTORATION

CORNER C 1/4 TWP 11S RANGE 29E

ORIGINAL SURVEY BY twp. surveyed by William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Not set

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
170 S. DAYTON - PH. 575-1251
JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2 1/2 x 30" iron post with brass cap.

From which:

A fir 25" diam., bears S39 1/2 W, 15.6 ft.
Mkd. C 1/4 S31 BT.

A pine 8" diam., bears N57W, 31.7 ft.
Mkd. C 1/4 S31 BT.

MONUMENT MARKED

GRANT COUNTY SURVEYOR

C 1/4 S 31

1969

LS 644

Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon, Steel tape and compass
Courthouse, Canyon City, Oregon 97820 Var = 20° East