

X


### CORNER RESTORATION

CORNER E $\frac{1}{4}$  TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



**ORIGINAL DESCRIPTION:**

Set stone 14"x 12"x 6"

**RESTORATION BY, STAMP AND DATE:**

**BAGETT & GRIFFITH SURVEYING**  
170 S. DAYTON - PH. 575-1251  
JOHN DAY, OREGON 97845

July 1969

REGISTERED  
**OREGON**  
LAND SURVEYOR

JULY 10, 1964  
DUANE I. GRIFFITH  
644

**EVIDENCE FOUND:**

NONE

**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:**

Show how trees are scribed and basis of bearings, including compass var.


Set 2 $\frac{1}{2}$ "x 30" iron post with brass cap.

From which:

A pine 16" diam. bears N89E; 12.2 ft.  
Mkd T11S R29E  $\frac{1}{4}$ S32BT

A fir 6" diam. bears S47W; 2.8 ft.  
Mkd T11S R29E  $\frac{1}{4}$ S31BT

MONUMENT MARKED  
GRANT COUNTY SURVEYOR



Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon, Steel tape & compass  
Courthouse, Canyon City, Oregon 97820 Var = 20° East