


CORNER RESTORATION

CORNER E $\frac{1}{4}$ TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Set: stone 14"x 10"x 8"

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:

NONE

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2 $\frac{1}{2}$ "x 30" iron pipe with brass cap.

From which:

A pine 8" diam. bears N76W; 2.7 ft.


Mkd T11S R29E $\frac{1}{4}$ S32BT

A pine 12" diam. bears N15E; 26.8 ft.

Mkd T11S R29E $\frac{1}{4}$ S33BT

MONUMENT MARKED

GRANT COUNTY SURVEYOR



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon, Steel tape & compass
 Courthouse, Canyon City, Oregon 97820 Var = 20° East