


CORNER RESTORATION

CORNER E 1/4 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Set stone 14" x 8" x 6"

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:


None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

- Set 2 1/2" x 30" iron pipe with brass cap.
- From which:
 - A pine 20" diam. bears S32E; 197.1 ft.
Mkd T11S R29E 1/4 S34 BT
 - A pine 18" diam. bears S10W; 161.5 ft.
Mkd T11s R29E 1/4 S33 BT

MONUMENT MARKED
GRANT COUNTY SURVEYOR



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon,
 Courthouse, Canyon City, Oregon 97820

Steel tape & compass
 Var. \neq 20° East