


CORNER RESTORATION

CORNER CS1/16 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: Twp. surveyed by William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Not set.

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
170 S. DAYTON - PH. 575-1251
JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2½x30" iron pipe with brass cap.


From which:

A fir 9" diam., bears N83E, 13.4 ft.
Mkd. CS1/16 S32 BT.

A pine 19" diam., bears S25E, 15.3 ft.
Mkd. CS1/16 S32 BT.

MONUMENT MARKED

Grant County Surveyor



Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon, Steel tape & compass
Courthouse, Canyon City, Oregon 97820 Var = 200 East