


CORNER RESTORATION

CORNER S1/16 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: Twp. surveyed by William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Not set.

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845

July 1969



EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2½"x 30" iron pipe with brass cap.


From which:

A pine 19" diam. bears S87W, 70.2 ft.
 mkd S1/16 S32 BT

A juniper 10" diam. bears N21E, 14.0 ft.
 mkd S1/16 S33 BT

MONUMENT MARKED

GRANT COUNTY SURVEYOR



Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon, Steel tape & compass
 Courthouse, Canyon City, Oregon 97820 Var.= 20° East