


CORNER RESTORATION

CORNER SW 1/16S35 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER: Unknown

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

None

RESTORATION BY, STAMP AND DATE: June, 1970

REGISTERED
OREGON
LAND SURVEYOR

Duane I. Griffith

JULY 10, 1964
DUANE I. GRIFFITH
644

EVIDENCE FOUND:


None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2½"x30" iron post with Brass Cap Mkd.:
From which:
A pine 12" diam. bears N30°E, 19.3 ft.
Mkd. SW 1/16 S35 BT
A pine 12" diam. bears West, 8.5 ft.
Mkd. SW 1/16 S35 BT

MONUMENT MARKED
Grant County Surveyor



Complete and File with Office of the Grant Steel tape & Compass
County Surveyor, Grant County, Oregon, Var.=20°East
Courthouse, Canyon City, Oregon 97820