


CORNER RESTORATION

CORNER 1/16 S35 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER: Unknown

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

None

RESTORATION BY, STAMP AND DATE:

June, 1970



EVIDENCE FOUND:


None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2½"x30" iron post with Brass Cap Mkd.:
 From which:
 A pine 19" diam. bears N52°E, 29.0 ft.
 Mkd. S1/16 S36 BT
 A pine 22" diam. bears S65°W, 7.2 ft.
 Mkd. S1/16 S35 BT

MONUMENT MARKED
 Grant County Surveyor



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon, Steel tape & Compass
 Courthouse, Canyon City, Oregon 97820 Var.=20° East