


## CORNER RESTORATION

CORNER SW TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



**ORIGINAL DESCRIPTION:**

Set stone 14x10x6" and one BT.

A tamarack 15" diam., bears S12E; 24 lks.

**RESTORATION BY, STAMP AND DATE:**

**BAGETT & GRIFFITH SURVEYING**

170 S. DAYTON - PH. 575-1251

JOHN DAY, OREGON 97845

July 1969



**EVIDENCE FOUND:**

Stone 14x12x6" with six notches on the N.E.S. & W. edges.

A dead tamarack 16" diam., bears S16E; 16.4 ft.  
Scribes visible.

**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:**

Show how trees are scribed and basis of bearings, including compass var.

Set 2½x30" iron post with brass cap.

From which:

A lodgepole pine 6" diam., bears N38½E; 22.2 ft.

Mkd. T11S R29E S31 BT.

A lodgepole pine 5" diam., bears N61W; 25.0 ft.

Mkd. T11S R28E S36 BT.


A fir 15" diam., bears S37W; 29.3 ft.

Mkd. T12S R28E S1 BT.

A fir 5" diam., bears S76E; 38.0 ft.

Mkd. T12S R29E S6 BT.

MONUMENT MARKED



Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon,

Courthouse, Canyon City, Oregon 97820

Steel tape and compass  
Var = 20° East