


CORNER RESTORATION

CORNER S $\frac{1}{4}$ TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER:

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Set stone 32x6x4"

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845



July, 1969

EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

Set 2 $\frac{1}{2}$ x30" iron post with brass cap.

From which:

- A fir 15" diam., bears N65E; 33.1 ft.
Mkd. $\frac{1}{4}$ S31 BT.
- A fir 9" diam., bears N58W; 18.6 ft.
Mkd. $\frac{1}{4}$ S31 BT.

MONUMENT MARKED



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon, Steel tape & compass
 Courthouse, Canyon City, Oregon 97820 Var = 20° East