


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

74

History of original corner establishment:

Corner not established in original survey



No record of subsequent monumentation found in County records  
Description of corner evidence found:

NONE

See survey dated October, 1981  
Description of monument and accessories established to perpetuate the original location of this corner:


At corner point I set a 2½ x 30 inch aluminum pipe with aluminum cap marked as shown 22 inches in the ground from which;

NEW BTs

A 13 inch P.Pine bears N74E, 21.3 feet marked E1/16 S5 BT

A 11 inch P.Pine bears S37E, 16.6 feet marked E1/16 S8 BT

Raised mound of stone 4 ft. at the base to top of cap



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Handwritten signature*

OREGON  
JULY 10, 1954  
DUANE I. GRIFFITH  
644

Date, October 2, 1981.

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. New BTs measured to center of tree.

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 23 day of Dec, 1981  
Robert D. Dugan by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)