


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

1298

C19

History of original corner establishment:
None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey...

Set 2 1/2" X 30" aluminum pipe with 2 1/2" aluminum cap 24" in the ground and surrounded with a mound of stone. Cap is marked as shown in corner diagram.

Set steel fence post 4.4 feet South of monument with sign 54-9 and 54-2 attached.

New bearing trees established:

- A 13" ponderosa pine bears North- 40.5 feet, scribed: C 1/4 S2 BT.
- A 11" ponderosa pine bears S51°E- 98.1 feet, scribed: C 1/4 S2 BT.
- A 9 1/2" ponderosa pine bears S19°W- 60.3 feet, scribed: C 1/4 S2 BT.
- A 17" ponderosa pine bears N33°W- 43.6 feet, scribed: C 1/4 S2 BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on August 26, 1993.

Compass declination 18° East.

| |
|---|
| REGISTERED PROFESSIONAL LAND SURVEYOR |
| <i>William R. Wells</i> |
| OREGON JULY 22, 1977 WILLIAM R. WELLS 1106 |

RENEWS 12-31-94

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 27 day of Jan, 1994
Robert D. Beyer by _____
 (COUNTY OFFICIAL) (DEPUTY)