CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey.

DIAGRAM



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner location determined by survey and single porportionate measurement between the NW corner of Sec. 6 and the SW cor. of Sec. 7, T7S, R31E.

At the corner point, we set a 2"x30" Galvanized Iron Pipe 6" in the ground to bedrock and supported in a mound of stone, 8 ft. dia. base to top of pipe, with brass cap attached, marked:

From which we mark new BT's:

A 16" Ponderosa Pine scribed "S 1/16 S1 BT" on a double blaze, bears S82°W 99.1 ft.

And a 16" Ponderosa Pine, scribed "S 1/16 S6 BT" on a double blaze, bears S42°E 108.2 ft.

Attached brass washer marked: "LS 1099" to lower blaze of new BT's.

Corner location monumented and perpetuated in accordance with our survey contract.



PLS 1099
1982

Magnetic compass (Declination 18½° East)
Steel Tape.

Witnesses: Gary Langlitz
Greg Orton
Jeff Anderson

September 2, 1982

REGISTERED PROFESSIONAL LAND SURVEYOR
Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of Surveyor *County of* Grant
State of Oregon, *I hereby certify that the within instrument was filed in this office for record on the* 25 *day of* Jan, *19* 83
Robert D. Baggett *by* .....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

D-1