


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

1298

D17

History of original corner establishment:
None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At position determined by survey...

Set 2 1/2" X 30" aluminum pipe with 2 1/2" aluminum cap, 26" in the ground and surrounded with a mound of stone. Cap is marked as shown in corner diagram.

Set steel fence post 3.0 feet South of monument with sign 54-9 and 54-2 attached.

New bearing trees:

- A 10" juniper bears S56°E- 39.1 feet, scribed: S 1/16 S2 BT.
- A 10" juniper bears N81°W- 23.2 feet, scribed: S 1/16 S3 BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 and 54-9, painted face of blaze and a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on August 26, 1993.

Compass declination 18° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

RENEWS 12-31-94

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 27 day of March, 1994
Robert D. Baggett by _____
 (COUNTY OFFICIAL) (DEPUTY)