


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

D19

History of original corner establishment:
None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey...

Set 2½" X 30" aluminum pipe with 2½" aluminum cap 26" in the ground and surrounded with a mound of stone. Cap is marked as shown in corner diagram.

Set steel fence post 4.0 feet North of monument with sign 54-9 and 54-2 attached.

New bearing trees established:

A 16" ponderosa pine bears S56½°W- 35.0 feet, scribed: CS 1/16 S2 BT.
A reference monument (5/8"X30" iron pin) bears N16°W- 20.7 feet, with 1½" plastic cap stamped 'WR Wells PLS 1106', wired sign 54-3 to pin.

New bearing tree has a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence post by reference monument with sign 54-9 attached.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on August 26, 1993.

Compass declination 18° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

RENEWS 12-31-94

Office of *Surveyor* County of *Grant*
State of *Oregon* I hereby certify that the within instrument was filed in this office
for record on the *7* day of *March*, 19*94*
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)