


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1881 by Meldrum & Campbell under General Land Office Contract No. 380. Surveyor General records state:
 Set a pine post for 1/4 Sec. corner from which a
 Pine 40 ins. diam. bears N54°E, 60 lks. dist.
 Pine 30 ins. diam. bears S24°East, 197 lks. dist.



Description of corner evidence found:

Found a small pile of small stones, but not the original corner post. Found a high stump with all scribing visible to the North of the corner. The South BT is a very low stump with BT scribing on the stump.

Description of monument and accessories established to perpetuate the

original location of this corner Set a 2"x14" galvanized pipe with 2 1/2" brass cap 8" in the ground to bedrock. Anchored the base with cement and mortared rock around the pipe 10" in diameter and 6" high. Surrounded monument with rock mound 8" high and 24" in diameter. Set a 4"x4"x6' redwood post 8" in ground and surrounded by dirt mound with some rock, 4' West of monument with signs 54-2 & 54-4 as guard post for the corner. Scalped bark and painted red band around new Bearing Trees and posted signs 54-3 with the following information:

	High Stump	S54°W	39.6'	New BT's were scribed	
	Low Stump	N24°W	130.0'	in upper blaze;	and in each lower blaze;
New	{ 12" P. Pine 16" D. fir	N84°E	80.5'	1/4 S11	BT, along with a
		S16°W	66.0'	1/4 S2	brass nail & washer stamped RLS 699

REGISTERED
PROFESSIONAL
LAND SURVEYOR

I hereby certify the above corner monument was re-established as herein described on October 26, 1974.


Leland Lee Myers
 OREGON
 JULY 9, 1965
 LELAND LEE MYERS
 699

74832

Office of *County Clerk* County of *Grant*

State of *OREGON*, I hereby certify that the within instrument was filed in this office for record on the *20* day of *Nov.* 1974 at *2:30* in *Book 1*, Page *194*

by *John J. Wells* (COUNTY OFFICIAL) by *Betty Dowary* (DEPUTY)



INDEXED

* SEE WELLS 3/94