


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

G19

History of original corner establishment:
None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey...

Set 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap 20" in the ground and surrounded with a mound of stone. Cap is marked as shown in corner diagram.

Set steel fence post 3.0 feet North of monument, with sign 54-2 and 54-9 attached.

New bearing trees established:

A 10" ponderosa pine bears N3 1/2°W- 43.5 feet, scribed: C 1/4 S11 BT.

A 18" ponderosa pine bears S25°W- 24.4 feet, scribed: C 1/4 S11 BT.

A 28" ponderosa pine bears S17 1/2°E- 75.6 feet, scribed: C 1/4 S11 BT.

A 12" juniper bears N34°W- 118.3 feet, scribed: C 1/4 S11 BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on August 19, 1993.

Compass declination 18° East.

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

RENEWS 12-31-94

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 4 day of Mar, 1994
Robert D. Baggett by _____
 (COUNTY OFFICIAL) (DEPUTY)