

RECEIVED AND
FILED

JUN 14 1973

JOHN LIVEIRA, County Clerk

BY *Robert D. Baggett* Deputy


CORNER RESTORATION

S. 1/4 cor.
CORNER Sec. 32 TWP 7S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: Frank W. Campbell

CONTRACT NUMBER: 380

CONTRACT DATE: March 19, 1881



ORIGINAL DESCRIPTION:

N. 89° 02' E., on a true N in bdy. of sec 5.

40.00 Set a basalt stone 22x7x6 and raised a mound of stone for 1/4 sec. cor.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

County Surveyor

May 5, 1973

EVIDENCE FOUND:

Found 2"x2 1/4" axle set in an old mound of stone, also found the original 1/4 corner stone in a rock jack about 18 ft. NW of the axle. The stone is a basalt stone 20"x8"x7" marked 1/4. I accept the position of the axle and the mound of stone, from which an unrecorded bearing tree, a 22" pine bears N. 22° W., 12.0 feet, scribed 1/4 S. This BT is in a E-W fenceline.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the Corner Point: Set a 1 1/2"x36" iron pipe 18" in the ground with brass cap marked as shown, from which NEW BEARING TREE:

MONUMENT MARKED

A juniper 8" diam bears S 65° E., 110.1 ft., scribed 1/4 S 5CS BT.

I placed the original corner stone East and alongside the iron pipe and raised a mound of stone to the top of the pipe.

Used compass with 20° east variation and steel tape measuring to the face of the blaze on the BTs.
Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

