


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Forest W. Campbell under G.L.O. Contract No. 380. Surveyor General records state:

Set Pine post from which:  
24" Y.Pine bears South 58 lks.  
15" Y.Pine bears N26°W 39 lks.



Description of corner evidence found:


No evidence of the original corner or its accessories exist.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2½" Brass Cap on 2½"x30" Gal. steel pipe marked as shown 24" in ground. No stone available.

From which:

8" Pine bears N2°E, 38.1 ft. scribed ¼ S34 upper blaze and a lower blaze scribed BT and with a Brass disk stamped PLS 896.  
14" Wh.Fir bears S36°W, 36.8 ft. scribed ¼ S3 upper blaze and a lower blaze scribed BT and with a Brass disk stamped PLS 896.  
Set steel guard post with sign 54-4 4 ft. West.  
Posted signs 54-4 and 54-3 on BT's.  
Painted red band around BT's and painted blazes red.



**REGISTERED PROFESSIONAL LAND SURVEYOR**

*Larry D. Bishop*

**OREGON**  
JULY 11, 1909  
**LARRY D. BISHOP**  
896

Office of *Surveyor* County of *Grant*  
State of *Oregon*, I hereby certify that the within instrument was filed in this office for record on the *23* day of *Jan* 1981.  
*Louise D. Dyer* by *[Signature]*  
(COUNTY OFFICIAL) (DEPUTY)

*Supersedes sheet filed 12-31-80*