


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-1

History of original corner establishment:

STONE 14x12x10 IN MOUND
32" TAMARACK N15°E 43LKS
8" FIR N12°W 57LKS
8" FIR S81°E 30LKS
72" RED FIR S8°W 18LKS



AARON F. YORK, CONTRACT #309, Nov. 18, 1878

Description of corner evidence found:

Stone 12 X 9 X 7

Badly rotted stump, BRS S 9 1/2° W (Record S8°W), 15.3 Ft. Distance (Record 18 Lks) with no scribing remaining.
Badly rotted stump, BRS. N23°W (Record N12°W), 36.0 Ft. Distance (Record 57 Lks) with no scribing remaining.
Stump 27" Dia., BRS. N16 1/2° E (Record N15°E) 27.8 Ft. Distance (Record 43 Lks) with axe work but no scribing remaining.

Description of monument and accessories I established to perpetuate the original location of this corner

Set 32" X 2" flanged iron pipe with brass cap marked:

Douglas Fir, 14" Dia., BRS. S24 3/4° E, 14.9 Ft. Distance.
Marked: T6S R26E S6 BT
Larch, 15" Dia., BRS. S59 1/4° W, 31.4 Ft. Distance.
Marked: T6S R25E SL BT
6' Iron Fence Post with "Attention" sign within 5' of Corner.

T6S R25E
S1 | S6
R25E R26E
T7S
1979
PLS 346

All BTs have BT tag, new 13Ts have painted red stripe and brass washer stamped: PLS 346; nailed to lower blaze.

Buried original stone along iron pipe.

Office of _____ County Surveyor _____ County of Grant
State of Oregon _____, I hereby certify that the within Instrument was filed in this office
for record on the 4 day of Oct 1979
Robert D. Bayliff by _____
(COUNTY OFFICIAL) (DEPUTY)

Corner updated
Filed Dec 1982
Form R6-7100-57 (9/71)

REGISTERED PROFESSIONAL LAND SURVEYOR
Wayne O. Harris
OREGON MAY 6, 1955
WAYNE O. HARRIS
346