


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

E-11

History of original corner establishment:

STONE 13X10X6 FOR  $\frac{1}{4}$  CORNER  
RAISED STONE MOUND

AARON F. YORK, CONTRACT #309, APRIL 4, 1879



Description of corner evidence found:

Stone 13 X 10 X 6 in mound.

Description of monument and accessories established to perpetuate the original location of this corner

Set 32" X 2" flanged iron pipe with brass cap marked:

Ponderosa Pine, 9" Dia., BRS. N39 $\frac{1}{2}$ <sup>0</sup>E, 62.4 Ft. Distance.

Marked:  $\frac{1}{4}$  S 4 BT

Ponderosa Pine, 13" Dia., BRS. S 6 $\frac{1}{2}$ <sup>0</sup>W, 66.8 Ft. Distance.

Marked:  $\frac{1}{4}$  S 9 BT

6' Iron Fence Post with "Attention" Sign within 5' of Corner.

T7S R26E  
 $\frac{1}{4}$  S4  
 S9  
 1979  
 PLS 346

All BTs have BT tag, painted red stripe and brass washer stamped: PLS 346; nailed to lower blaze.

Buried original stone along side iron pipe.

Office of ..... County Surveyor ..... County of Grant .....  
 State of Oregon ..... , I hereby certify that the within instrument was filed in this office  
 for record on the 4 day of Oct 1979 .  
 Robert O Bayett by .....  
 (COUNTY OFFICIAL) (DEPUTY)

