


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

V-9

History of original corner establishment:

Stone 24X13X6 in Stone Mound



Description of corner evidence found:

Badly fragmented stone 19 X 13 X 6 in stone mound.

Description of monument and accessories established to perpetuate the original location of this corner

Set 32" X 2" flanged iron pipe with brass cap marked:

T7S R26E
 S29 | S28
 S32 | S33
 1979
 PLS 346

Ponderosa Pine, 23" Dia., BRS. N78°E, 20.2 Ft. Distance.

Marked: T7S R26E S28 BT

Ponderosa Pine, 14" Dia., BRS. S 4¼°E, 23.4 Ft. Distance.

Marked: T7S R26E S33 BT

Douglas Fir, 7" Dia., BRS. S79½°W, 12.1 Ft. Distance.

Marked: T7S R26E S32 BT

White Fir, 13" Dia., BRS. N45°W, 16.2 Ft. Distance.


Marked: T7S R26E S29 BT

6' Iron Fence Post with "Attention" sign within 5' of Corner.

All BTs have BT tag, painted red stripe and brass washer stamped: PLS 346; nailed to lower blaze.

Buried original stone alongside iron pipe.

Office of County Surveyor County of Grant
Oregon
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 4 day of Oct 1979.
Robert D. Baggett by _____
 (COUNTY OFFICIAL) (DEPUTY)



V-9