


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index No. J-19

History of original corner establishment:

The corner was originally established by Frank W. Campbell under Contract No. 521 Dated January 8, 1885. The notes state that at the corner a 20" x 8" x 5" marked basalt stone was set 15" in the ground and a mound of stones was raised alongside.



No record of subsequent remonumentation found in County Records .
Description of corner evidence found:

None. Corner re-established by single proportion measure.

Description of monument and accessories established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 18 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence post east of corner and attached signs 54-2 and 54-4.

Established 2 new BT's:

A 13" juniper bears N 77° E, 267.5 feet scribed $\frac{1}{4}$ S 11 BT.

A 16" pine bears S 39° W, 67.6 feet scribed $\frac{1}{4}$ S 14 BT.

New BT's have a lower blaze scribed BT with a brass washer stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 and painted a 6" red band around BT's above the upper blaze.


Used steel tape and magnetic compass with 19 $\frac{1}{2}$ ° east declination . Measured to center of Bts.
See map of survey.

This corner set September 19, 1979.

Witnesses: D. Kaufman, PLS
G. Flowers, LSIT
B. English
B. Reynolds

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells
OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106



Office of County Surveyor County of Grant
State of Oregon , I hereby certify that the within instrument was filed in this office
for record on the 15 day of Oct 1979
Robert D. English by _____
(COUNTY OFFICIAL) (DEPUTY)