


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Refer to: Plat of Wilson 1985 Cadastral Survey  
Section 29, T.7S., R.27E., W.M.

History of original corner establishment:

No record of previous monumentation.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner point I set a 2 1/2" X 30" alum. pipe with a 3" alum. cap containing a magnet and marked:

I built a stone mound around the monument.

S29  
C-N-SE-SE  
1/256  
PLS 1832  
1986

From the corner:

- A Ponderosa Pine, 21" dia., S10°E, 49.3 ft. marked: X at breast height and BT at base.
- A Ponderosa Pine, 25" dia., S68 1/2°E, 41.3 ft. marked: C N SE SE 1/256 S29 BT

BTs have blaze and a 6" stripe painted red, a BT tag, a "Land Survey Monument" sign and an alum. "PLS 1832" washer nailed to the bottom of the blaze. There is a 6' steel fence post with a "Land Survey Monument" sign within 5' of the corner.

Measured to center of BTs using steel tape and staff compass. Magnetic declination set at 17 3/4°E.

April 18, 1986

Office of..... *Savvy* ..... County of..... *Grant* .....

State of..... *Arizona* ..... I hereby certify that the within instrument was filed in this office

for record on the..... *25* day of..... *July* ..... 19..... *86*

..... *Robert D. Bayless* ..... by..... *Fayette S. Munro* .....

(COUNTY OFFICIAL) (DEPUTY)

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 13, 1979  
FAYETTE S. MUNRO  
1832