

CORNER RESTORATION

S 1/16 cor.
between secs.


CORNER 5 and 6 TWP 7S RANGE 29EWM

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:

This corner not previously
established.



ORIGINAL DESCRIPTION:

None.

RECEIVED AND
FILED

APR 13 1988

OFFICE OF COUNTY SURVEYOR
Attest: *Jack L. [Signature]*

RESTORATION BY, STAMP AND DATE:

R.D. Bagett
J.L. Watson
D. Buck

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1953
ROBERT D. BAGETT
598

March 17, 1988

EVIDENCE FOUND:

None.

See Map of Survey No. 1033.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

This corner is established by survey at midpoint
between the section corner common to secs. 5, 6, 7, & 8, and the $\frac{1}{4}$ corner common to secs. 5 & 6. **MONUMENT MARKED**


At the corner point:

Drove a $\frac{5}{8}$ " x 30" iron reinforcing rod 15 ins. to bed-
rock, and surrounded rod with a mound of stone,

from which I scribe NEW BEARING TREES:

A mountain mahogany, 6 ins. diam., bears N. 50° E.,
30.5 ft., marked X BT.

A juniper, 18 ins. diam., bears S. 51° E., 30.5 ft.,
marked S1/16 S5 BT.



Attached B G A bearing tree tags to BT's. Used magnetic compass with
20° E. var. and steel tape, measuring distance to 40d nail driven
in side center of BT's. at root crown.