CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original Survey by Meldrum and Campbell
Contract No. 380, 1881.

Set a Pine Post for 1/4 Sec. Cor.

Pine 40 in. dia. bears N43°E 118 lks. Dist.

Fir 20" in dia. bears S55°W 29 lks. Dist.

DIAGRAM

34

1/4 — T6S
T7S R31E

3

Description of corner evidence found:

The remains of the original BT's.
A 26" Douglas Fir snag, previously opened, scribing "S" visible; and an approximate 20" Pine stump, rotten, no marks visible. No trace remains of the original Pine post corner monument. At the corner we find a 2 1/2" Iron Pipe, extending 6" above ground, with brass cap attached, marked: From Which the remains of the original BT's:
A 26" D. Fir snag bears S55°W 19.1 ft., and a 20" rotten Pine stump bears N43°E 77.9 ft., and new BT's apparently marked by BLM. A 10" Douglas Fir, with scribing "1/4 S 34 BT" visible on a single blaze bears N6°E 45.9 ft. And a 12 Douglas Fir with scribing 1/4 S3 BT" visible on a single blaze bears S80°E 30.7 ft.

U.S. Dept. of the Interior
Bureau of Land Management
T6S R31E

1/4 S34
S3

T7S

1980

Description of monument and accessories I established to perpetuate the original location of this corner:

Staff Compass & Steel Tape

Declination 19°East

July 29, 1982

Witnesses: Gary Langlitz
Greg Orton
Jeff Anderson

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 25 day of Jan, 19 83
Robert D. Bright by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

A-15