


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

1298

E18

History of original corner establishment:
None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey...

Set 2 1/2" X 30" aluminum pipe with 2 1/2" aluminum cap 28" in the ground and surrounded with a mound of stone. Cap is marked as shown in corner diagram.

Set steel fence post 3.0 feet North of monument with sign 54-9 and 54-2 attached.

New accessories established:

A 4X3X1 1/2 foot basalt outcrop bears N20°E-42.3 feet, marked: 'XBO', 1.0 foot above ground, on South face.

A 24" douglas fir bears S66 1/2°E- 90.4 feet, scribed: W 1/16 S11 BT.

New bearing tree has a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. XBO has sign 54-3 anchored at base of stone, measured to 'X', and painted marking red.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on August 25, 1993.

Compass declination 18° East.

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

RENEWES 12-31-94

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 25 day of Mar, 1994
Robert D. Gage by _____
 (COUNTY OFFICIAL) (DEPUTY)