


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
None. This corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At a position determined by survey, which is 40 feet Westerly of and perpendicular to the visual centerline of State Highway 395...

Set a 2 1/2" aluminum cap on 2 1/2"X30" aluminum pipe, 26" in the ground with a mound of stone to cap, marked as shown in corner diagram.

New bearing trees established:

A 8" ponderosa pine bears N 26° E - 77.3 feet, scribed: S 10 CC BT

A 24" ponderosa pine bears S 56 1/2° W - 70.3 feet, scribed: S 10 CC BT

New bearing trees have a brass washer stamped 'PLS 1106' nailed to face of blaze, attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on September 7, 1993.

Compass declination 18° East.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

renews 12-31-94

Office of *Surveyor* County of *Grant*  
State of *Ore gon* I hereby certify that the within instrument was filed in this office  
for record on the *4* day of *Mar*, 19*94*  
*Robert D. Baggett* by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)