


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

0-23

History of original corner establishment:

Kurt Weaver,, PLS 1679, set a 2 1/2" x 30" flanged galvanized iron pipe with a 2 1/2" brass cap marked as shown below. Monument was exposed 8" in a mound of stone. From the corner:

- A Douglas Fir, 9" dia., N21°52'E, 28.0 ft..
- A Douglas Fir, 11" dia., S38°10'E, 29.6 ft..



Description of corner evidence found:

I found a 2 1/2" galvanized iron pipe with a 2 1/2" brass cap marked: in a mound of stone..

T7S R31E
C
N1/16 | S24
C
LS 1679
1980

From the corner:

- A Douglas Fir, 13" dia., S38 1/4°E, 29.6 ft.; with scribing visible.
- A Douglas Fir, 9" dia., with scribing visible, uprooted; bearing and distance to the root hole fit the record.

Description of monument and accessories I established to perpetuate the original location of this corner:

To maintain the corner I marked a new BT:

A Douglas Fir, 16" dia., N82 1/2°E, 17.5 ft.; marked: CN1/16 S24 BT

BTs have blaze and a 6" band painted red, BT tags and "Land Survey Monument" signs. New BT has, additionally, an alum. "PLS 1832" washer nailed to the bottom of the blaze. There is a 6' steel fence post with a "Land Survey Monument" sign within 5' of the corner.

Measured to center of BTs using steel tape and staff compass. Magnetic declination set at 16°E.

August 21, 1989

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Fayette S. Munro

**OREGON
JULY 13, 1979
FAYETTE S. MUNRO
1832**

**RECEIVED AND
FILED**

DEC 17 1989

OFFICE OF COUNTY SURVEYOR
[Signature]
 Attest: _____

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

~~FILED~~